



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

ENGINEERING CHANGE REQUEST

ECR 387

Date Opened: 4/11/22 1:30 PM
Type: Drawing/Pattern Change
Priority: Medium
Status: Quality Disposition
Reason:
Expense: 0
Target Date:
Execution Date:
ECR Approval No:

Requested By: Drouin, Steven
Responsible Engineer: Drouin, Steven
Requester*: McMachen, Lisa
DE Approver*: Shepherd, David
ECR Lead*: Drouin, Steven

RE (R&D):
Status Note:

****BRIEF DESCRIPTION**:** **D189-1005 Cable cutter**
DESCRIPTION/ ADR CONTENT:** This is a issue is with Leonardo and Dart not Labelling Leonardo part Numbers on DART Manufactured parts before leaving the Hawkesbury facility.

CUSTOMER APPROVALS

Customer	Customer Visible	Customer Approval Required	*	Customer Approved
----------	------------------	----------------------------	---	-------------------

PARTS

Part No	Rev	Part Status	Name	Type	Customer Part	Special Comments	Documents
D189-1005-011		Obsolete	AW189 Cable Cutter System	Finished Good			
D189-1005-013		On hold	AW189 Cable Cutter System	Finished Good			IIN-D189-1005-RevD.pdf
D189-1005-015		On hold	AW189 Lower Cable Cutter System	Finished Good	D189-1005-015		D189-1005
D4970-041		On hold	Windshield Deflector Assembly	Sub-assembly	D4970-041		D4970-RevD.pdf
D4982-041		On hold	Upper Cutter Assembly	Sub-assembly	D4982-041		D4982-RevD.pdf
D5904-041		On hold	Lower Cutter Assembly	Finished Good			D5904-RevA.pdf

INVENTORY DISPOSITION

Part No Revision	Material No	Current Inventory Qty	Purchasing On-Order Qty	Qty Scheduled for Production
D189-1005-011		0 Quarantine	0 *	0 *
D189-1005-013		0 Quarantine	0 *	0 *
D189-1005-015		1 Quarantine	0 *	7 *
D4970-041		0 Quarantine	0 *	0 *
D4982-041		3 Quarantine	0 *	0 *
D5904-041		1 Quarantine	0 *	8 *

EFFECTS

Effect Group	Effects
2. ECR Lead Assessment - Impacted Docs & Output	Drawing Change Required
3. ECR Lead Assessment - Status During ECR	Active - No Under Review
4. Production Type	In-house production
5A. ECR Lead Assessment - MINOR Changes	Correction of drawing errors
7. Final Impacts	Paperwork Update, Parts Must Comply